

6-keto-Prostaglandin F_{1a} EIA Kit Product Number: EA08

Revision Date: 11/13/08

Page 1 of 7

MSDS: 6-keto-Prostaglandin $F_{1\alpha}$ EIA Kit Product No. EA08

This EIA Kit, is provided and produced by Oxford Biomedical Research as an in vitro diagnostic test kit for the sole purpose of research use.

Manufacturer:

Oxford Biomedical Research 2165 Avon Industrial Dr. Rochester Hills, MI 48309 (248) 852-8815

Section 1 - Hazardous Components:

Component: EIA Buffer	Hazardous Content: None
Extraction Buffer	None
HRP Conjugate	None
Standard	None
TMB Substrate	Substrate Ingredient 1
Wash Buffer	None

Section 2 - Physical and Chemical Characteristics:

EIA Buffer:

Boiling Point: ~100°C Vapor Pressure: Not Determined Vapor Density: Not Determined Solubility in Water: Soluble

Extraction Buffer:

Boiling Point: ~100°C Vapor Pressure: Not Determined Vapor Density: Not Determined Solubility in Water: Soluble Specific Gravity: Not Determined Melting Point: N/A Evaporation Rate: Not Determined Appearance: Clear Liquid

Specific Gravity: Not Determined Melting Point: N/A Evaporation Rate: Not Determined Appearance: Clear Liquid

HRP Conjugate:

Boiling Point: ~100°C Vapor Pressure: Not Determined Vapor Density: Not Determined Solubility in Water: Soluble

Standard:

Boiling Point: ~100°C Vapor Pressure: Not Determined Vapor Density: Not Determined Solubility in Water: Soluble

TMB Substrate:

Boiling Point: 81°C Vapor Pressure: 0.29 mm Hg @ 20°C Vapor Density: 3.4 (Air = 1) Solubility in Water: Soluble

Wash Buffer:

Boiling Point: ~100°C Vapor Pressure: Not Determined Vapor Density: Not Determined Solubility in Water: Soluble Specific Gravity: Not Determined Melting Point: N/A Evaporation Rate: Not Determined Appearance: Clear Liquid

Specific Gravity: Not Determined Melting Point: N/A Evaporation Rate: Not Determined Appearance: Clear Liquid

Specific Gravity: $1.033 (H_20 = 1)$ Melting Point: N/A Evaporation Rate: Not Determined Appearance: Clear Liquid

Specific Gravity: Not Determined Melting Point: N/A Evaporation Rate: Not Determined Appearance: Clear Liquid

Section 3 - Fire and Explosion Hazard Data:

EIA Buffer:

Flash Point: Not DeterminedSpecial Fire Fighting Measures: NoneUnusual Fire and Explosion Hazards: Carbon monoxide may be produced upon heating.Auto-Ignition Temperature: Not DeterminedExplosion Limits:Upper: Not Determined

Extraction Buffer:

Flash Point: Not DeterminedSpecial Fire Fighting Measures: NoneUnusual Fire and Explosion Hazards: Carbon monoxide may be produced upon heating.Auto-Ignition Temperature: Not DeterminedExplosion Limits:Upper: Not DeterminedLower: Not Determined

HRP Conjugate:

Flash Point: Not DeterminedSpecial Fire Fighting Measures: Dry Chemical, CO2, Water SprayUnusual Fire and Explosion Hazards: Carbon monoxide may be produced upon heating.Auto-Ignition Temperature: Not DeterminedExplosion Limits:Upper: Not DeterminedLower: Not Determined

Standard:

Flash Point: Not Determined
Special Fire Fighting Measures: Dry Chemical, CO₂, Water Spray
Unusual Fire and Explosion Hazards: Carbon monoxide may be produced upon heating.
Auto-Ignition Temperature: Not Determined
Explosion Limits: Upper: Not Determined
Lower: Not Determined

TMB Substrate:

Flash Point: 103.9°C (187°F)
 Special Fire Fighting Measures: Dry Chemical, CO₂, Water Spray
 Unusual Fire and Explosion Hazards: Carbon monoxide and nitrogen oxides may be produced upon heating.
 Auto-Ignition Temperature: Not Determined
 Explosion Limits: Upper: 9.5% Lower: 1.3%

Wash Buffer:

Flash Point: Not Determined
 Special Fire Fighting Measures: Dry Chemical, CO₂, Water Spray
 Unusual Fire and Explosion Hazards: Carbon monoxide and nitrogen oxides may be produced upon heating.
 Auto-Ignition Temperature: Not Determined
 Explosion Limits: Upper: Not Determined Lower: Not Determined

Section 4 – Reactivity Hazard Data:

EIA Buffer: Stability: Stable Conditions to Avoid: N/A Hazardous Polymerization: Will Not Occur Hazardous Decomposition/Byproducts: Carbon monoxide or carbon dioxide may be produced upon heating. Material Incompatibility: Strong Oxidizing Agents

Extraction Buffer:

Stability: Stable Conditions to Avoid: N/A Hazardous Polymerization: Will Not Occur Hazardous Decomposition/Byproducts: Carbon monoxide or carbon dioxide may be produced upon heating. Material Incompatibility: Strong Oxidizing Agents

HRP Conjugate:

Stability: Stable Conditions to Avoid: N/A Hazardous Polymerization: Will Not Occur Hazardous Decomposition/Byproducts: Carbon monoxide or carbon dioxide upon heating.

Material Incompatibility: Strong Oxidizing Agents

Standard:

Stability: Stable Conditions to Avoid: N/A Hazardous Polymerization: Will Not Occur Hazardous Decomposition/Byproducts: Carbon monoxide or carbon dioxide may be produced upon heating. Material Incompatibility: Strong Oxidizing Agents,

TMB Substrate:

Stability: Stable Conditions to Avoid: N/A Hazardous Polymerization: Will Not Occur Hazardous Decomposition/Byproducts: Carbon monoxide, carbon dioxide, or nitrogen oxides may be produced upon heating. Material Incompatibility: Strong Oxidizing Agents

Wash Buffer:

Stability: Stable Conditions to Avoid: N/A Hazardous Polymerization: Will Not Occur Hazardous Decomposition/Byproducts: Carbon monoxide, carbon dioxide, or nitrogen oxides may be produced upon heating. Material Incompatibility: Strong Oxidizing Agents

Section 5 - Health Hazard Data:

EIA Buffer:

LIA DUIRI.		
Exposure Limits:	OSHA PEL: N/A	ACGIH TLV: N/A
Toxicity Data:	N/A	
Health Hazards:	None Known	
Chronic Exposure:	N/A	
Target Organs:	None Known	
First Aid:	Ingestion: Wash mouth out with water if conscious and seek immediate medical attention.	
	1	o fresh air and seek immediate medical Give oxygen if breathing is difficult.
		n water for 15 minutes and seek immediate on if irritation occurs. Remove clothing.
	•	ter for 15 minutes while lifting ek immediate medical attention.

Extraction Buffer:

Exposure Limits:	OSHA PEL: N/A	ACGIH TLV: N/A
Toxicity Data:	N/A	
Health Hazards:	None Known	
Chronic Exposure:	N/A	
Target Organs:	None Known	
First Aid:	Ingestion: Wash out n	nouth with water if conscious and seek
	immediate	medical attention.
	Inhalation: Expose to	fresh air and seek immediate medical
	attention.	Give oxygen if breathing is difficult.
		water for 15 minutes and seek immediate n. Remove contaminated clothing.
		e
	•	er for 15 minutes while lifting k immediate medical attention.
	eyends and see	a miniourate metalear attention.

HRP Conjugate:

Exposure Limits:	OSHA PEL: N/A	ACGIH TLV: N/A
Toxicity Data:	N/A	
Health Hazards:	None Known	
Chronic Exposure:	N/A	
Target Organs:	None Known	
First Aid:	Ingestion: Wash out	mouth if conscious and seek immediate
	medical a	ttention.
	Inhalation: Expose to	o fresh air and seek immediate medical
	attention.	Give oxygen if breathing is difficult.

Skin: Flush area with water for 15 minutes and seek medical attention if irritation persists.

Eyes: Flush area with water for 15 minutes while lifting eyelids and seek immediate medical attention.

Standard:

Exposure Limits:	OSHA PEL: N/A	ACGIH TLV: N/A
Toxicity Data:	N/A	
Health Hazards:	None Known	
Chronic Exposure:	N/A	
Target Organs:	None Known	
First Aid:	Ingestion: Wash out n	nouth with water if conscious and seek
	immediate	medical attention.
	Inhalation: Expose to	fresh air and seek immediate medical
	attention.	Give oxygen if breathing is difficult.
	Skin: Flush area with	water for 15 minutes and seek immediate
	medical attentio	n. Remove contaminated clothing.
	Eyes: Flush with wate	er for 15 minutes while lifting
	eyelids and seel	k immediate medical attention.

TMB Substrate:

Exposure Limits:	OSHA PEL: N/A ACGIH TLV: N/A		
Toxicity Data:	N/A		
Health Hazards:	Direct contact with eyes, mucus membranes, skin, or		
	respiratory track may cause irritation.		
Chronic Exposure:	Overexposure may cause reproductive disorders.		
Target Organs:	Eyes, Skin, Reproductive Organs		
First Aid:	Ingestion: Wash out mouth with water if conscious and seek immediate medical attention.		
	Inhalation: Expose to fresh air and seek immediate medical		
	attention. Give oxygen if breathing is difficult.		
	Skin: Flush area with water for 15 minutes and seek immediate		
	medical attention. Remove contaminated clothing.		
	Eyes: Flush with water for 15 minutes while lifting		
	eyelids and seek immediate medical attention.		

Wash Buffer:

Exposure Limits:	OSHA PEL: N/A	ACGIH TLV: N/A
Toxicity Data:	N/A	
Health Hazards:	None Known	
Chronic Exposure:	N/A	
Target Organs:	None Known	
First Aid:	e	nouth with water if conscious and seek medical attention.
	-	fresh air and seek immediate medical Give oxygen if breathing is difficult.
		water for 15 minutes and seek immediate on. Remove contaminated clothing.
	-	er for 15 minutes while lifting k immediate medical attention.

Section 6 - Control Measures:

Respiratory Protection: None required with proper ventilation. Ventilation: Requires local exhaust. Protective Gloves: Proper disposable gloves. Eye Protection: Safety glasses or goggles. Other Protective Equipment: Uniform, lab coat, or disposable lab wear. Work/Hygienic Practices: Follow usual precautionary measures for handling chemicals. Keep away from food and beverages.

Section 7 - Handling and Use Precautions:

Accidental Release Measures: Wear suitable protective equipment to prevent inhalation, ingestion, or skin and eye contact. Clean up spills with a sponge, mop, or vermiculite.

Waste Disposal: Disposal shall be in accordance with local, state, or federal guidelines.

Handling and Storage: 4-8°C

The information provided in this document is believed to be correct, but does not purport to be all-inclusive. This document is to serve only as a guide. Oxford Biomedical Research shall not be held liable for damages resulting from handling or contact with the above product(s). The contents of this document are not reflective of or a substitute for state, municipal or insurance requirements and constitute no warranty of any kind.